

## Excess Tools Part List & Accessories Declaration Form

**Transaction Type** : Retirement for Sale/Trade In/Scrap/Intercompany/Temporary Storage

**Tool ID** : 92H8156-AZ

**Date** : 05 September 2018

**a. General**

Cat	Description
<b>Vendor / Supplier</b>	Electroglass
<b>Model</b>	4090
<b>Process</b>	8" wafer test
<b>Vintage (Year of Manufacture)</b>	2004
<b>Serial No.</b>	HE99030508-21879
<b>Asset Description</b>	
<b>Tool Status</b>	Cold shutdown
<b>Software Version</b>	n/a
<b>CIM</b>	n/a

**b. Hardware Configuration (Fab)**

Cat	Description	Qty / Units	Status, tick if ok[✓ ]
<b>Main System</b>	4090 prober chasis	1	ok[✓ ]
<b>SMIF System</b>			
<b>Handler System</b>			
<b>Options</b>			
<b>Others (Pls specify if any)</b>			

**c. Hardware Configuration (Subfab / Auxilliary Units)**

Sub Accessories / Auxilliary Units	Qty / Units	Status, tick if ok[✓ ]

**d. Missing/Faulty Parts / Accesories List**


**(If NO missing/faulty parts/accessories please indicate NA)**


Description	Qty / Units	
Tool was functional when powered down. Appears to be missing a lot of parts, not possible to inventory missing parts		
<b>Total Estimated USD</b>		

## Tool Photos (Photos must make sense to show all the major parts intact)


**Tool ID** : 92H8156-AZ  
**Date** 9/5/2018

### a. General

Description	Photos
<b>Eqpt ID</b>	

<p><b>Vendor / Supplier / Model</b>  <b>INCLUDE A PHOTO OF THE SERIAL NUMBER TAG THAT IS AFFIXED TO THE TOOL.</b></p>	
---------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------

### b. Hardware Configuration (Fab)

Description	Photos
<b>Main System</b>	
<b>SMIF System</b>	
<b>Handler System</b>	
<b>Chambers</b>	na
<b>Others</b>	na

### c. Hardware Configuration (Subfab / Auxilliary Units)

Description	Photos
	NA

### d. Missing Parts [photos showing major missing parts]

Description	Photos
	NA

## Equipment Configuration

<b>Eqpt ID</b>	<b>92H8156-AZ</b>
<b>Tool Status</b>	<b>Cold Idle</b>
<b>Chamber Components</b>	